



Incremental SRA (ISRA)



UNCLAS



USS GRAVELY (DDG 107)



USS COLE (DDG 67)




USS Mesa Verde (LPD 19)

Ballast Tank Repair



UNCLAS





USS Mesa Verde (LPD 19)

Line Shaft Bearing Repairs



UNCLAS





TSRA

All the Time Readiness



UNCLAS



- Increased the Assessment Completion rate by **19.8%** and the Find to Fix rate by **109%**

UNCLAS

Mid-Atlantic RMC

We Fix Ships!



USS Mitscher (DDG 57)

Tail Shaft Repairs




UNCLAS



12 x external
bolt holes

5 x internal guide
pin holes





USS Pasadena (SSN 752)

MARMC Diver Mishap



UNCLAS



UNCLAS

Mid-Atlantic RMC

We Fix Ships!



USS Iwo Jima (LHD 7)


In-Water Rudder Installation




UNCLAS



Innovative solutions to support on-time delivery



Internal cofferdam assembly



Rudder/stock rigged/raised under hull



Questions?



UNCLAS

